

at the next engine overhaul after the effective date of this AD, but not later than December 31, 2002, in accordance with Turbomeca Service Bulletin (SB) 292 72 0150, dated April 10, 1992, or in accordance with SB 292 72 0153, dated February 22, 1993, respectively. Installation of this hardware constitutes terminating action to the checks required by this AD.

(e) The checks required by paragraphs (a) and (b) of this AD may be performed by the pilot holding at least a private pilot certificate as an exception to the requirements of part 43 of the Federal Aviation Regulations (14 CFR part 43). The checks must be recorded in accordance with Sections 43.9 and 91.417(a)(2)(v) of the Federal Aviation Regulations (14 CFR 43.9 and 14 CFR 91.417(a)(2)(v)), and the records must be maintained as required by the applicable Federal Aviation Regulation.

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

**Note:** Information concerning the existence of approved alternative method of compliance with this AD, if any, may be obtained from the Engine Certification Office.

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

(h) The actions required by this AD shall be done in accordance with the following Turbomeca SB's:

Document No.	Pages	Date
292 72 0150 .....	1-4	April 10, 1992.
Total pages: 4.		
292 72 0153 .....	1-5	February 22, 1993.
Total pages: 5.		

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Turbomeca 64511 Bordes Cedex—France. Copies may be inspected at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

(i) This amendment becomes effective on June 21, 1995. Issued in Burlington, Massachusetts, on May 15, 1995.

**James C. Jones,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 95-12329 Filed 5-18-95; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF DEFENSE

### Department of the Navy

#### 32 CFR Part 706

#### Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972; Amendment

**AGENCY:** Department of the Navy, DOD.

**ACTION:** Final rule.

**SUMMARY:** The Department of the Navy is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (Admiralty) of the Navy has determined that USS CARNEY (DDG 64) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with certain provisions of the 72 COLREGS without interfering with its special functions as a naval ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

**EFFECTIVE DATE:** May 2, 1995.

**FOR FURTHER INFORMATION CONTACT:** Commander K.P. McMahon, JAGC, U.S. Navy, Admiralty Counsel, Office of the Judge Advocate General, Navy Department, 200 Stovall Street, Alexandria, VA 22332-2400, Telephone number: (703) 325-9744.

**SUPPLEMENTARY INFORMATION:** Pursuant to the authority granted in 33 U.S.C. 1605, the Department of the Navy amends 32 CFR Part 706. This amendment provides notice that the Deputy Assistant Judge Advocate General (Admiralty) of the Navy, under authority delegated by the Secretary of the Navy, has certified that USS CARNEY (DDG 64) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with the following specific provision of 72 COLREGS without interfering with its special function as a naval ship: Annex I, paragraph 3(a), pertaining to the location of the forward

masthead light in the forward quarter of the ship, and the horizontal distance between the forward and after masthead lights; Annex I, paragraph 2(f)(i), pertaining to the placement of the masthead light or lights above and clear of all other lights and obstructions; and Annex I, paragraph 3(c), pertaining to placement of task lights not less than 2 meters from the fore and aft centerline of the ship in the athwartship direction. The Deputy Assistant Judge Advocate General (Admiralty) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR Parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

#### List of Subjects in 32 CFR Part 706

Marine safety, Navigation (Water), and Vessels.

Accordingly, 32 CFR Part 706 is amended as follows:

#### PART 706—[AMENDED]

1. The authority citation for 32 CFR Part 706 continues to read as follows:

**Authority:** 33 U.S.C. 1605.

2. Table Four of § 706.2 is amended by:

a. Adding the following vessel to Paragraph 15:

Vessel	Number	Horizontal distance from the fore and aft centerline of the vessel in the athwartship direction
USS CARNEY	DDG 64	1.90 meters.

b. Adding the following vessel to Paragraph 16:

Vessel	Number	Obstruction angle relative ship's headings
USS CARNEY	DDG 64	1.05.06 thru 112.50°.

3. Table Five of § 706.2 is amended by adding the following vessel:

TABLE FIVE

Vessel	No.	Masthead lights not over all other lights and obstructions. annex I, sec. 2(f)	Forward masthead light not in forward quarter of ship. annex I, sec. 3(a)	After masthead light less than 1/2 ship's length aft of forward masthead light. annex I, sec. 3(a)	Percentage horizontal separation attained
USS CARNEY .....	DDG 64	X	X	X	20.4

Dated: May 2, 1995.

**K.P. McMahon,**

*CDR, JAGC, U.S. Navy, Deputy Assistant Judge Advocate General (Admiralty).*

[FR Doc. 95-12475 Filed 5-19-95; 8:45 am]

BILLING CODE 3810-FF-P

**32 CFR Part 706**

**Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972; Amendment**

**AGENCY:** Department of the Navy, DOD.  
**ACTION:** Final rule.

**SUMMARY:** The Department of the Navy is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (Admiralty) of the Navy has determined that USS SAIPAN (LHA 2) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with certain provisions of the 72 COLREGS without interfering with its special functions as an amphibious support ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

**EFFECTIVE DATE:** March 22, 1995.

**FOR FURTHER INFORMATION CONTACT:**

Commander K.P. McMahon, JAGC, U.S. Navy, Admiralty Counsel, Office of the Judge Advocate General, Navy Department, 200 Stovall Street, Alexandria, VA 22332-2400, Telephone number: (703) 325-9744.

**SUPPLEMENTARY INFORMATION:** Pursuant to the authority granted in 33 U.S.C. 1605, the Department of the Navy amends 32 CFR Part 706. This amendment provides notice that the Deputy Assistant Judge Advocate General (Admiralty) of the Navy, under authority delegated by the Secretary of the Navy, has certified that USS SAIPAN (LHA 2) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with the following specific provisions of 72 COLREGS without interfering with its special function as an amphibious support ship: Annex I, paragraph 3(a) pertaining to the horizontal distance between the forward and after masthead lights; Rule 21(a) pertaining to placement of masthead lights over the fore and aft centerline of the vessel; Annex I, paragraph 2(g) pertaining to the placement of sidelights above the hull of the vessel; Annex I, paragraph 3(b) pertaining to placement of the sidelights in front of the forward

masthead light. The Deputy Assistant Judge Advocate General (Admiralty) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR Parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

**List of Subjects in 32 CFR Part 706**

Marine safety, Navigation (Water), Vessels.

Accordingly, 32 CFR Part 706 is amended as follows:

**PART 706—[AMENDED]**

1. The authority citation for 32 CFR Part 706 continues to read as follows:

**Authority:** 33 U.S.C. 1605.

**§ 706.2 [Amended]**

2. Table Two of § 706.2 is amended by revising the entry for USS SAIPAN to read as follows:

TABLE TWO

Vessel	Number	Masthead lights, distance to stbd of keel in meters; Rule 21(a)	Forward anchor light, distance below flight dk in meters; § 2(K), Annex I	Forward anchor light, number of; Rule 30(a)(i)	AFT anchor light, distance below flight dk in meters; Rule 21(e), Rule 30(a)(ii)	AFT anchor light, number of; Rule 30(a)(ii)	Side lights, distance below flight dk in meters; § 2(g), Annex I	Side lights, distance forward of forward masthead light in meters; § 3(b), Annex I	Side lights, distance inboard of ship's sides in meters; § 3(b), Annex I
USS SAIPAN .....	LHA-2	10.1	.....	1	.....	1	2.8	72.1	.....

3. Table Five of § 706.2 is amended by revising the entry for USS SAIPAN to read as follows: